

RECEIVED

JAN 20 1993

DIVISION OF
OIL GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) Jan 1992 To (mo./yr.) Jan 1993
2. DOGM File Number: M/023/023
3. Mine Name: Henry #1 and #2 Mine
4. Mineral(s) Mined: Gypsum
5. Legal Description (Location of Lands Affected):
SE 1/4, NW 1/4, Section 19, Township 15S, Range 1E
SW 1/4, NE 1/4, Section 19, Township 15S, Range 1E
NW 1/4, SE 1/4, Section 19, Township 15S, Range 1E
6. Name of Operator or Company: H.E. Davis and Sons
7. Permanent Address: 525 W. Arrowhead Trail
Spanish Fork, Utah 84660

8. Company Representative (or designated operator):

Name: Harold E. Davis
Title: President
Address: 525 W. Arrowhead Trail, Spanish Fork, Utah
Phone: 798-7355

- ☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 22,386 tons

3. How much new or additional acreage was affected during past year? none

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Removal of gypsum ore within designed pit area only.

A sediment impoundment dam was completed in the main stream drainage near the mouth of the canyon. Approximately 3,000 yds³ of clay material and 400 tons of rip rap was hauled in to build the dam. The volume of gypsum mined was approx. 27,000 tons.

5. How much acreage was reclaimed during past year? 1.4 acres

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Seeding 1.4 acres with seed mix the forest service told us to use. Method used after contouring the area to blend in with surrounding hills and ruffing the area with bulldozer

tracks to hold the seed and moisture. The seed was then spread with a hand crank seed spreader strapped to an individual. It is too early to evaluate - 2 - results. Seeding was done during Oct. 1992.

7. What is the total disturbed acreage at years end? 4.7 acres
8. Briefly summarize mining and reclamation planned for the upcoming year.
No reclamation planned. Mining approximately 20,000 tons.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted. (No changes)
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached. (None)

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Harold E. Davis

Title of Operator: President

Signature of Operator: *Harold E. Davis*

Date: Jan. 14, 1993

jb
MR-AR